

February 5, 1985

TO: Coal File, Inspection and Enforcement Folder
FROM: David Lof, Mining Field Specialist **DL**
RE: Co-op Mining Company, Bear Creek Canyon Mine, ACT/015/025
Folder #7, Emery County, Utah

On January 24, 1985, I conducted a partial inspection at the above mentioned site. I was not accompanied on the inspection due to its brevity.

I inspected the drainage controls in the scalehouse area, specifically the cross culvert inlet to the sediment basin. This area had been cited in Notice of Violation N84-4-2-1, which was terminated January 16, 1985. At the time of my inspection, runoff was flowing unobstructed to the culvert inlet.

The downspout for the disturbed area runoff from the coal storage yard down to the shop pad remained frozen. At the time of my inspection, it appeared that the runoff from the coal storage yard had breached the headwall berm for the downspout inlet and it was flowing beneath the culvert down to the shop pad.

wj

cc: Mel Coonrod, Co-op Mining Co.
Donna Griffin, OSM
Joe Helfrich, DOGM

Statistics:

See Genwal Coal Company, Crandall Canyon Mine memo dated
February 4, 1985

0072Q-47